TERRY BAKER
electrical contractor

130a Godinton Road, Ashford, Kent TN23 1LJ
T 01233 665107 F 01233 665142 E info@tbelectrical.org.uk W www.tbelectrical.org.uk

Mr Senna
Charing House
Canterbury Road
Gillingham
Kent
ME7 5AY

Monday 13th June 2016

Dear Mr Senna

Site Visit: Friday 10th June 2016
Engineer: Jason Hammill

After carrying out a visual inspection of the bunker at Charing House, Canterbury Road, our engineer has advised;

'An Industrial ventilation unit is in place, The Ventilation unit was turned on and checked, all working well. No signs of mould or damp throughout the bunker.'

Although, we would recommend a full service of the ventilation machine to check the fans and filters as this is recommended to be done every 12-18months. This is just to ensure that the machine lasts its lifetime and stays working efficiently.

Kind Regards

Lauren Gray
contracts Manager